

August 24, 2021

Concrete for PCCP Joint Repair

Specification Reference: 509.02

SM Material Code 509M00010

Prepackaged concrete patching materials for partial depth repairs and bottom-half of slab repairs at PCCP joints shall be identified as Grade 3U18 and 3U58 and shall meet the requirements as stated in 509.04 and 509.04(a).

Source Code	Manufacturer Product Name	Approval Number	Criteria
8950	BLUESTONE PRODUCTS, A TCC MATERIALS Co. Tenon Concrete Patching Mix (formerly ProSpec)	-----W219500	<i>Meets 3U18</i>
8950	BLUESTONE PRODUCTS, A TCC MATERIALS Co. Tenon Air-Entrained Concrete Patching Mix AE (formerly ProSpec)	-----W219501	<i>Meets 3U58</i>